

Work Order ID 58681

May 14, 2010 10:50:30 AM



Page 1

Item ID: D3372-5

Accept



Setup Start



Revision ID:

Stop



Item Name: Cam Lock Shaft

Start Date: 5/14/10 Start Qty: 18.00



Cust Item ID:

Required Date: 5/17/10 Req'd Qty: 18.00



Customer:

Reference: SCRAP-OLD REV

Approvals: Process Plan:

Date:

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Draw
Number

Draw
Rev.

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

Draw Nbr

Revision Nbr

D3372

Rev B

145

0.00



Small Fab

Memo

0.00

Small Fab

PULL FROM STOCK:
18 X D3372-5 B22167
SCRAP/DESTROY -OLD REV

SB 10/05/20



150

QC21- Final Inspection - Work Order Release

0.00



QC

Memo

0.00

Quality Control

10/05/20

W 10/05/20

Picklist Print

May 14, 2010 10:50:28 AM

Page 1

Work Order ID: 58681



Parent Item: D3372-5



Parent Item Name: Cam Lock Shaft

Start Date: 5/14/10

Required Date: 5/17/10

Comments: IPP A 05.01.18 New issue: KJ/JLM

Start Qty: 18.00

Required Qty: 18.00

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Qty Issued	Date Issued	Status
D3372-5		Manufactured	No				Each	28.0000				



Cam Lock Shaft

Location

Loc Qty

Loc Code

ST052

28

22167 ✓

18

22290

5

58654

5

SB 12/05/20


Linda,

Scrap these, they are the old Rev. They are no longer used. I Issue A w/o for (5) Rev B.

J.P.



DESIGN <i>[Signature]</i>	DRAWN BY <i>[Signature]</i>	DART AEROSPACE LTD HAWKESBURY, ONTARIO, CANADA	
CHECKED <i>[Signature]</i>	APPROVED <i>[Signature]</i>	DRAWING NO. D3372	REV. A SHEET 6 OF 9
DATE 05.01.10		TITLE COLLECTIVE LOCK	SCALE 2:1



UNDER REVIEW

05.02.21

RELEASED

05/02/11

